EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S16	1	"20060130947"	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/06/06 15:53
S17	3846	148/666,420.ccls. OR 420/402-414.ccls. OR 72/274-291.ccls.	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/06/09 12:45
S18	245	S17 AND (Mg OR magnesium) AND (wire OR screw OR bolt) AND draw$3	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/06/09 12:46
S19	187	S17 AND (Mg OR magnesium) AND (wire OR screw OR bolt) AND draw$3 AND wire	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/06/09 12:49
S20	70	S17 AND (Mg OR magnesium) AND wire AND (screw OR bolt) AND draw$3	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/06/09 12:49
S21	14	S17 AND magnesium AND wire AND (screw OR bolt) AND draw$3	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/06/09 12:50
S22	13	"4990198"	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/06/09 12:59
S23	15	"4997622"	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/06/09 12:59
S24	12	"4887951"	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/06/09 13:09
S25	6165	magnesium AND wire AND (screw OR bolt) AND draw$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/06/09 13:12
S26	1611	magnesium AND (screw OR bolt) AND (draw$3 SAME wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/06/09 13:13

S27	512	(magnesium SAME (screw OR bolt)) AND (draw$3 SAME wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/06/09 13:13
S28	16	(magnesium SAME (screw OR bolt)) AND (draw$3 SAME wire) AND tensile AND grain	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/06/09 13:14
S29	68	(magnesium SAME (screw OR bolt)) AND (draw$3 SAME wire) AND tensile	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/06/09 13:14
S30	6598	(magnesium SAME (screw OR bolt))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/06/09 13:34
S31	67	(magnesium NEAR10 (screw OR bolt)) SAME draw$3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2008/06/09 13:35

6/9/2008 4:39:16 PM
C:\Documents and Settings\vvelasquez\My Documents\EAST\Workspaces\10561536.wsp